



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Date: 08/11/2009

Reviewed: LR

Mine Name: Fantasy Land Jasper	Permit Number: S0270096
Operator Name: David Penny	Inspection Date: 04/22/2009
Inspector(s): Tom Munson	Time: 11:00AM
Other Participants:	Mine Status: Inspect for release

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$2,600 Nationwide Financial Guarantee **Acreage permitted:** 5.0 acres

Purpose of Inspection:

To perform a site release inspection.

Inspection Summary:

The site was visited and it appeared that the site was very well graded. Since the area had been rehabbed from the Milford Flat Fire of 2007, the mine site had evidence of good vegetation and desirable species.

Photos were taken of the site.

Conclusions and Recommendations:

The site can be released based on the fact that revegetation has been accomplished within practical limits.

Inspector's Signature

Thomas Munson

TM

cc: (OPERATOR)

Jerry_mansfield@blm.gov

Opie_abayta@blm.gov

O:\M027-Millard\S0270096-FantasyLand\inspections\insp-04222009.doc

S02700024 – Fantasy Land Jasper
Photos taken April 22, 2009



It was hard to determine that the area around the site burned in the Milford Flat fire.



The site was well graded and had some positive vegetative growth.



Main downhill slope.



Upper pad area.